

VEHICLE INSPECTION REPORT

DA69DMF

Daf CF 340

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	01/01/2020	VIN	XLRASM4100G283128	Axle Combi	6x2
Year	2020	Body Style	Box Van	Rear Suspension	Air
Mileage	547,593 Km Warranted	MOT Due	31/03/2026	Rear Doors	Roller
Fuel Type	Diesel	Cab Type	SPACE CAB	Tail Lift	Column
Colour	WHITE	Gearbox	AUTOMATIC		

WARNING LIGHT ON DASH REAR LIFT

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Radio/CD
- Cloth seat trim


Photos








Condition Check



Damage Photos



1: Seat Base Cover nsf
Soiled
Heavy



2: Dash Warning Lights
Displayed
No Action



3:

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-

EML light illuminated	Fault
ABS light illuminated	OK